



A1 AMERICAN
QUALITY SERVICE VALUE
— SINCE 1911 —



CARE INSTRUCTIONS

SHEETS

WASHING & DRYING INSTRUCTIONS:

- Machine wash in warm water, on a normal cycle with a maximum temperature of 60°C (140°F).
- Use mild detergent and non-chlorine bleach only.
- Tumble dry low on permanent press setting, maximum temperature of 55°C (131°F).
- Remove sheets promptly to reduce wrinkling.
- Use cool iron, if necessary.
- Wash colors separately and separate from other linens such as towels.
- Wash heavily soiled items separately from lightly soiled items.