



A1 AMERICAN
QUALITY SERVICE VALUE
— SINCE 1911 —



CARE INSTRUCTIONS

PILLOWS

WASHING & DRYING INSTRUCTIONS:

- Machine wash in cool water, on a delicate cycle in a large-capacity front-load washing machine with a maximum temperature of 30°C (86°F).
- Do not overfill washing machine.
- Use mild detergent and do not use fabric softeners or conditioners.
- Do not bleach.
- Tumble dry on low permanent press setting, with a maximum temperature of 55°C (131°F).
- Use a dryer ball when drying pillows. A dryer ball will maintain movement of the pillow, allowing for faster and more even drying.
- Ensure items are completely dry before storing and re-fluff before storage or before use. Do not store in plastic.
- Wash heavily soiled items separately from lightly soiled items